



CE330 CURING TIME CHART

MINIMUM CURING TIME (HRS.)

TEMPERATURE (°F)	40	45	50	55	60	65	70	75	80	90
CE330 REGULAR	16	12	10	8	6	5	4	3	3	2
CE330 WITH ACCELERATOR*	12	10	8	6	4					
CE330 LOW TEMPERATURE	8	6	5	4	3					

- Accelerator dose: one qt per 10-gal mixed CE330. Or 3 OZ per one-gal mixed CE330.